

Mid-Landing STEPTREAD Solutions

These existing landings need to be removed, new framing installed, covered with CDX plywood, then 1/2" Durock. Next our 1" thick tiles are thin-set down and grouted with color- matched grout.



Mid landings at a Waipio condo. These pics were on a rainy day. Landings can't be level, or algae and slippage result.



Contrast this landing nosing to the softer nosing examples to the right.

STEPTREAD Rehab Solutions



These landings were rehabbed using our nosing tread, and 12 X 12 matching landing tiles. ONE NAPILI above, MAKANI A KAI below, on our web.



Another solution is 12" wide landing planks, on the WEHILANI in Waikoloa Village, a new project.



BUILDING SYSTEMS HAWAII

Ph: 808 885 0987 • 800 353 0934
web: buildingsystemshawaii.com