


STEPTREAD JOB TOUR KONA COAST RESORT

78-6842 Alii Drive, Kona



"Before" with new STEPTREADS shrink wrapped as they come from the factory, to be installed after the old treads are removed. Then refurbishing & paint to the color motif at bottom. Here's a close up of why their wood treads were replaced—to prevent lawsuits, cut maintenance, and entice buyers.



Below and left is what their new STEPTREADS look like. The closeup shows our "Granada Natural" Del Rio exposed aggregate. Non-slip, yet walkable with bare feet. The protruding bullnose aids visibility when descending.

Facilities & Grounds Mgr. Doug Branch replaced with his in-house crew, 2100 worn treads in the 28 acre site. 2 men averaged daily about 1 flight of 14 treads, including painting & replacing wood as necessary.

"STEPTREADS are the perfect answer for us. They're less expensive than wood and a lot better looking. No more painting. And they're a lot quieter!"



Hawaii Distributor:

BUILDING SYSTEMS HAWAII
808 885-0987 • 800 353-0934